SOFTWARE INSTALLATION GUIDE

1.Make sure computer is linked with machine via the USB wire already

2.Click the properties of “COMPUTER”, then clik the “DEVICE MANAGER”





2.In “DEVICE MANGER”interface,find the USB device ,Then click “UPDATE DRIVER SOFTWARE”



3.**Click”Browse” and go to the drive filer position ,****\Support win xp and win7 32 digital**



4.Click the file folder of *\Support win xp and win7 32 digital system\JCZDdriverAllinone and install the software**






Device Manager
File Action View Help
Update Driver Software - USBLMCV2
Installing driver softwar
Windows Security
Would you like to install this device software?
Name: BeiJing JCZ Technology CO., LTD
Publisher: BeiJing JinChengZi Technology Co.,LTD
Always trust software from "BeiJing JinChengZi Technology Co.,LTD".
Install
Don't Install
You should only install driver software from publishers you trust. How can I decide which device software is safe to install?


Device Manager
File Action View Help
Update Driver Software - USBLMCV2
Installing driver software...


Device Manager
File Action View Help
Update Driver Software - Laser Mark Control Board V2 [USB]
Windows has successfully updated your driver software
Windows has finished installing the driver software for this device:
Laser Mark Control Board V2 [USB]
Close


Device Manager
File Action View Help
Admin-PC
BJJCZ Device
Laser Mark Control Board V2 [USB]
Computer
Disk drives
Display adapters
Human Interface Devices
IDE ATA/ATAPI controllers
Mice and other pointing devices
Monitors
Network adapters
Ports (COM & LPT)
Processors
Sound, video and game controllers
System devices
Universal Serial Bus controllers
INSTLLATION DONE

==========END==========